



Micro-Bioretention Planter Box Detailed Plan View PB-7-A,B,C,D









	Micro	-Bioretenti	on Planter Box Faci	lity PB-7-A,B,C, and [Design Information		
ID	Descriptor		Facility PB-7-A	Facility PB-7-B	Facility PB-7-C	Facility PB-7-D	
Elev. "A"	Top of Planting	Design	463.50'	463.50'	463.00'	462.00'	
	Media	As-Built					
Elev. "B"	Top of Sand	Design	460.00'	460.00'	459.50'	458.50'	
		As-Built					
Elev. "C"	Top of Gravel	Design	459.50'	459.50'	459.00'	458.00'	
		As-Built					
Elev. "D"	PVC Underdrain	Design	458.50'	458.50'	458.00'	457.00'	
	Invert	As-Built					
Elev. "E"	Bottom of	Design	458.25'	458.25'	457.75'	456.75'	
	Aggregate	As-Built					
Elev. "F"	Weir/Overflow and ESDv Elev.	Design	464.50'	464.50'	463.50'	462.50'	
		As-Built					
	10-Year Ponding Elev.	Design	464.83'	464.84'	463.84'	462.71'	
Elev. "H"		As-Built					
	Min. Top of Wall	Design	464.50'	464.50'	464.00'	463.00'	
Elev. "G"		As-Built					
Facility Surface Area		Design	573 sq. ft.	281 sq. ft.	364 sq. ft.	313 sq. ft.	
		As-Built					
Total Perforated Underdrain Length for PB-		Design	1,490 cu. ft.	731 cu. ft.	764 cu. ft.	537 cu. ft.	
		As-Built					
		Design	106.00'				
		As-Built					
Red	Receiving Storm Drain Str.		214	214	214	214	
					i		

*See Detailed Plan Views & Details for More Information

NOTE: Contractor shall confirm that dimensions, inflow locatoins, roof leader locations and other design elements of ALL ESD/SWM facilities as shown on these plans are coordinated with architectural and other trade plans. If any discrepancies are found, the Contractor is to contact the design engineer and architect prior to proceeding with construction. Site utilities are to be constructed in locations shown. If a utility location is changed and is found to conflict with a ESD/SWM facility, the facility must be reviewed and approved by the County, Design Engineer, Architect and appropriate trade prior to utility construction. Modifications to the Stormwater Management Plan will require a formal revision to the plan with the Montgomery County Department of Permitting Services, which will include applicable plan revision fees, and may not be acceptable.

CONSTRUCTION INSPECTION CHECK-OFF LIST FOR MICRO BIORETENTION FACILI	TY PB-	7-A	PB-	7-B	PB-	7-C	PB-	7-D
STAGE	MCDPS INSPECTOR	OWNER/ DEVELOPER	MCDPS INSPECTOR	OWNER/ DEVELOPER	MCDPS INSPECTOR	OWNER/ DEVELOPER	MCDPS INSPECTOR	OWNER/ DEVELOPER
MANDATORY NOTIFICATION: Inspection and approval of each practice is required at these points prior to proceeding with construction. The permittee is required to give the MCDPS Inspector twenty-four (24) hours notice (DPS telephone 311). The DPS inspector may waive an inspection and allow the owner/developer to make the required inspection per a prior scheduled arrangement which has been confirmed with the DPS inspector in writing. Work completed without MCDPS approval may result in the permittee having to remove and reconstruct the unapproved work. Upon completion of the project, a formal Stormwater Management As-Built must be submitted to MCDPS unless a Record Drawing Certification has been allowed instead. Each of the steps listed below must be verified by either the MCDPS Inspector OR the Owner/Developer.	INITIALS/DATE	INITIALS/DATE	INITIALS/DATE	INITIALS/DATE	INITIALS/DATE	INITIALS/DATE	INITIALS/DATE	INITIALS/DATE
Excavation for Micro Bioretention facility conforms to approved plans								
Placement of stone backfill and underdrain system conforms to approved plans								
3. Placement of filter media conforms to approved plans								
4. Connecting pipes and/or grading conveyance to the facility constructed per the approved plans								
Final grading and permanent stabilization conforms to approved plans								

Design Engineer SWM Construction Observation Requirements	
The contractor is required to contact the Design Engineer at (301) 670-0840 with at least 24 hours advance notice at the following stages of Micro-Bioretention (MB), Micro-Bioretention w/ Impervious Liner (MB(L)), Planter Box Micro-Bioretention (PB), and/or Bio-Swale (BS) facility construction:	

Failure to notify the Design Engineer may necessitate SWM facility reconstruction.

 Facility excavation: MB, MB(L), BS • Concrete slab and wall form work: PB Installation of impervious liner: MB(L) Aggregate installation Underdrain layout and installation

 Sand layer installation Planting media installation SWM plantings and landscaping installation

BIORETENTION FACILITY MAINTENANCE SCHEDULE			
TASK	RECOMMENDED INTERVAL		
INSPECT AND REPAIR SOIL EROSION	MONTHLY AND AFTER HEAVY RAINS		
REMOVE LEAVES, DEBRIS, TRASH, SILT, ETC. & REPLACE MULCH LAYER	MINIMUM 2 TIMES PER YEAR (SPRING AND FALL)		
INSPECT PLANTS FOR DAMAGE & DISEASE/PEST PROBLEMS PRUNE AND TREAT PLANTS AS NEEDED & AS APPROPRIATE PER SPECIES. REMOVE AND REPLACE DEAD AND DISEASED PLANTS CONSIDERED BEYOND TREATMENT	MINIMUM 2 TIMES PER YEAR (3/15-4/30 and 10/1-11/30)		

SEE C4.11 FOR:

BIORETENTION FACILITY MAINTENANCE SCHEDULE				
TASK	RECOMMENDED INTERVAL			
NSPECT AND REPAIR SOIL EROSION	MONTHLY AND AFTER HEAVY RAINS			
REMOVE LEAVES, DEBRIS, TRASH, SILT, ETC. & REPLACE MULCH LAYER	MINIMUM 2 TIMES PER YEAR (SPRING AND FALL)			
NSPECT PLANTS FOR DAMAGE & DISEASE/PEST PROBLEMS PRUNE AND TREAT PLANTS AS NEEDED & AS APPROPRIATE PER SPECIES. REMOVE AND REPLACE DEAD AND DISEASED	MINIMUM 2 TIMES PER YEAR (3/15-4/30 and 10/1-11/30)			

2. SAND SPECIFICATIONS

3. BIORETENTION AREA PLANTING SOIL DOCUMENTATION REQUIREMENTS

4. MICRO—BIORETENTION AREA SPECIFICATIONS

SM#285890

SC#286335 SC013PB7ABCD

SWM PB-7-A,B,C,D PLAN VIEW AND DETAILS

ARCHITECT

9211 CORPORATE BLVD, SUITE 340

ROCKVILLE, MD 20850 301-770-0177(P) 301-330-3224(F)

MACRIS, HENDRICKS & GLASCOCK 9220 WIGHTMAN RD, SUITE 120 **MONTGOMERY VILLAGE, MD 20886** 301-670-0840(P)

STRUCTURAL COMPREHENSIVE STRUCTURAL SOLUTIONS 9220 WIGHTMAN RD, SUITE 120 **MONTGOMERY VILLAGE, MD 20886**

MECH./ELECTRICAL/PLUMBING

240-200-5599(P)

JAMES POSEY ASSOCIATES

410-265-6100(P) **KITCHEN NYIKOS-GARCIA**

11155 RED RUN BLVD, SUITE 310

BALTIMORE, MD 21117

FOODSERVICE DESIGN, INC 18219-A FLOWER HILL WAY **GAITHERSBURG, MD 20879** 240-683-9530 (P)

SUSTAINABILITY DOO CONSULTING, LLC

531 PICCADILLY ROAD

BALTIMORE, MD 21204

443-653-3792 (P)

CONSTRUCTION MANAGER SKANSKA USA BUILDING INC.

700 KING FARM BLVD, SUITE 200 ROCKVILLE, MD 20850 301-795-3100 (P)

Professional Certification. hereby certify that these documents were prepared or approved by me, and that I am a duly licensed Professional Enegineer under the laws of the State of Maryland, License No.: 16905, Expiration Date: 4.21.2022.

PROFESSIONAL SEAL:

PRINTS ISSUED

BID DOCUMENTS 10/21/2020 ADDENDUM #2 11/25/2020 ADDENDUM #3 ADDENDUM #4 12/03/2020

> WSSC 224NW09 TAX MAP FT62 PLAT 12762

9TH ELECTION DISTRICT CITY OF GAITHERSBURG, MD

GAITHERSBURG CLUSTER ELEMENTARY

SCHOOL #8

MONTGOMERY COUNTY PUBLIC

SHEET TITLE: SOIL EROSION, SEDIMENT CONTROL **AND STORMWATER**

MANAGEMENT PLAN

SHEET NO:

Sheet 13 of 28